



--Chris Goeben -- 262.202.3000--

## Satellite Inspection Report

---

Course Name:	Glacier Wood Golf Club
Contact Name:	Noah Carrick
Contact Number:	715-445-3391
Contact Email:	gwgc.supt@gmail.com

---

Course Address:

604 Water St, Iola Wi 54945

---

Scope of Work: Satellite Box was in good working order, all wiring checked, protection in place, and all stations tested to make sure that they ran correctly. Station 35 has no wiring to it, tested the station in the box and works properly

---

Checklist		Notes			
Satellite ID #'s		ID #1	1	ID #2	2
Satellite Type	Par +ES	Two-wire	New Par+ES box		
Satellite Location	Between holes 13/14				
Is Satellite box working	Yes	All Componets in good working order			
Electircal Input	120				
Any Parts Need to be replaced	No				
Is labeling In Cover	Yes	Station labeling is on a laminated sheet in box			
Is Surge Protection In Place	Yes	Maxi Surge Pipe is in place, hooked up, and tested good			
Any Damage to Box	No	Box looks to be in good shape			
Is box moisture protection in place	Yes	Lid shuts properly and drainage tubes are in place			
Insect Prevention In Place	Yes, But replaced	Nuvum strip was in box but replaced at time to freshen up			
Rodent Prevention In Place	Yes, But replaced	Bait blocks were in place, but replaced to freshen up			
Satellite Box Cleaned	Yes	Inside of box was vaccumed out, outside of box wiped clean			
Is Grounding in Good Condition	Yes	All grounding tested insdie of box to make sure working properly			
All Wiring Checked	Yes	checked all station connections on terminal boards, all wiring connections on power interconnect board, output station module, and two wire board			

Possible Number of Stations	48
Number of Stations Used	47
Station # and Notes	
1	Wiring in good shape and station tested properly
2	Wiring in good shape and station tested properly
3	Wiring in good shape and station tested properly
4	Wiring in good shape and station tested properly
5	Wiring in good shape and station tested properly
6	Wiring in good shape and station tested properly
7	Wiring in good shape and station tested properly
8	Wiring in good shape and station tested properly
9	Wiring in good shape and station tested properly
10	Wiring in good shape and station tested properly
11	Wiring in good shape and station tested properly
12	Wiring in good shape and station tested properly
13	Wiring in good shape and station tested properly

14	Wiring in good shape and station tested properly
15	Wiring in good shape and station tested properly
16	Wiring in good shape and station tested properly
17	Wiring in good shape and station tested properly
18	Wiring in good shape and station tested properly
19	Wiring in good shape and station tested properly
20	Wiring in good shape and station tested properly
21	Wiring in good shape and station tested properly
22	Wiring in good shape and station tested properly
23	Wiring in good shape and station tested properly
24	Wiring in good shape and station tested properly
25	Wiring in good shape and station tested properly
26	Wiring in good shape and station tested properly
27	Wiring in good shape and station tested properly
28	Wiring in good shape and station tested properly

29	Wiring in good shape and station tested properly
30	Wiring in good shape and station tested properly
31	Wiring in good shape and station tested properly
32	Wiring in good shape and station tested properly
33	Wiring in good shape and station tested properly
34	Wiring in good shape and station tested properly
35	No wiring to station, station does work properly
36	Wiring in good shape and station tested properly
37	Wiring in good shape and station tested properly
38	Wiring in good shape and station tested properly
39	Wiring in good shape and station tested properly
40	Wiring in good shape and station tested properly
41	Wiring in good shape and station tested properly
42	Wiring in good shape and station tested properly
43	Wiring in good shape and station tested properly

44	Wiring in good shape and station tested properly
45	Wiring in good shape and station tested properly
46	Wiring in good shape and station tested properly
47	Wiring in good shape and station tested properly
48	Wiring in good shape and station tested properly



